



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 12/08/2014


Reviewed 

Mine Name: Blue Castle	Permit Number: S/015/0077	Mine Status: Active
Operator Name: Goldterra Inc.	Inspection Date: 12/08/2014	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 9:40 - 10:00 am	Bond Amount: \$12,000
Attendee(s):	Weather: mild and clear	Bond Escalation: 03/20/2014
Inspection Purpose: Routine inspection		Prior Inspection: 10/30/2014

Conclusions and Recommendations

The purpose of the inspection was to determine if the site met the minimum requirements for bond release. The Operator has not formally requested bond release but did make know to the Division that the site would be reclaimed.

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds The permit and bond are current	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls) There are no underground openings or highwalls at the site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages/Erosion Control Erosion will be controlled by earthwork. Vegetation in the area is limited. Most of the erosion is controlled by surface shapes.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material None on site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety) Road from the pavement to the site was reclaimed by pocking	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts) The pit was backfilling and the surrounding area graded to blend into the surrounding area.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils Soils were not stockpiled prior to disturbance. Operator used materials on site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation Site will be seeded.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M015-Emery/S0150077-BlueCastle/inspections/Insp12082014.pdf



	<p>Access road to site was pocked. Looking west</p>
	<p>Access road to site pocked. Looking north.</p>
	<p>Looking north. Pit was backfilled and area blended into the surrounding area.</p>
	<p>Looking northeast. Area was prepared for seeding by using track marks.</p>